

2018-11-22

The ESAB administrative system was unable to produce a certificate at time of despatch for the delivery detailed below.



## INSPECTION CERTIFICATE

# E99

Acc to: EN 10204 - 3.1

Date: 2018-11-22

Cert no:

Our order: 2105687  
Our ref: Web user - Movex CMP020 BDE  
Cust no: DEB00816  
Your date: 2018-11-22

Your order: 125499  
Your ref:  
Your fax:  
Your e-mail:

### DELIVERED PRODUCT

Brand:  
Desc: OK Tigrod 316LSi 2,0x1000  
Item no: **163220R150**  
Lot no: **PVS455537551**  
Quantity: 25

The goods have passed production controls and certificates will be sent to the following address under separate cover

Delivery address

PAWLOWSKI GMBH

OGGENHAUSER HAUPTSTRASSE  
77

89522  
HEIDENHEIM-OGGENHAUSEN

Please refer any questions to:

ESAB Welding & Cutting GmbH  
Robert-Bosch-Straße 20

D-61184 Karben